National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 12/14/1992

ΑN	C91	IF/	\ 01	8

File No. 1951	12/21/1990	FALSE PASS, AK	Aircraft Reg No.	N9444F	Ti	me (Local): 12:20 AST
Engine Make/Mode Aircraft Damag Number of Engine Operating Certificate(s Name of Carrie	s: 1 b): Commuter Air Carrier r: MARKAIR EXPRESS n: Scheduled; Domestic;	Passenger/Cargo ommuter	Crew Pass	Fatal 1 0	Serious 0 0	Minor/None 0 0
	nt: COLD BAY , AK n: Same as Accident/Inci y: Off Airport/Airstrip	dent Location		Weathe Basie Lowe Wind Temper Obst	est Ceiling: 5 Visibility: 2	Witness Visual Conditions 500 Ft. AGL, Overcast 2.00 SM 130 / 030 Kts 4 Fog
Pilot-in-Command Ag	e: 51			Flight Ti	me (Hours)	
Certificate(s)/Rating(s) Airline Transport; Multi-engine La Instrument Ratings Airplane	and; Single-engine Land		Т	Las Total M	All Aircraft: 1 st 90 Days: 1 ake/Model: 3 ment Time: 9	186 323

THE FLIGHT DEPARTED COLD BAY FOR THE APRX 15 MIN FLT TO FALSE PASS. THERE ARE NO WX REPORTING FACILITIES AT FALSE PASS. COLD BAY WX WAS 4,500 FT OVCST, LIGHT RAIN & FOG; FORECAST CALLED FOR FREQ CEILINGS BELOW 1,000 FT. WRECKAGE LOCATED BETWEEN TWO MOUNTAINS. FALSE PASS WX ESTIMATED 400 FT OVCST, 2-3 MI IN RAIN & FOG, WINDS 25-30 KTS. FISHING BOAT CAPTAIN IN AREA ESTIMATED WINDS DOWN THE MOUNTAIN AT 60 MPH OR GREATER.

Brief of Accident (Continued)

ANC91FA018

File No. 1951 12/21/1990 FALSE PASS, AK Aircraft Reg No. N9444F Time (Local): 12:20 AST

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: MANEUVERING

Findings

1. (F) WEATHER CONDITION - LOW CEILING

2. (F) WEATHER CONDITION - RAIN

3. (F) WEATHER CONDITION - HIGH WIND

4. (F) TERRAIN CONDITION - MOUNTAINOUS/HILLY

5. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND

6. (C) AIRCRAFT CONTROL - UNCONTROLLED - PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

THE PILOT'S IMPROPER DECISION TO CONTINUE FLIGHT INTO AN AREA OF MOUNTAINOUS TERRAIN AND ADVERSE WEATHER CONDITIONS. THE TERRAIN AND WEATHER WERE FACTORS.